



**GEOTECHNICAL & MATERIALS  
ENGINEERING, TESTING & INSPECTION**  
P.O. BOX 15732 • TAMPA, FLORIDA 33684 • 813/872-7821 CA No.1450

**SIEVE ANALYSIS**

**PROJECT:** Product Check - P.O. No. 7001-95000  
53<sup>rd</sup> St. Yard

**PROJECT NO:** TL-8047

**CLIENT:** Transcor Recycling LLC

**DATE:** 3/27/2020

**LAB NO.:** B-11995

**SAMPLE LOCATION:** Stockpile

**SAMPLE DESCRIPTION:** Crushed Concrete Fines

<u>Sieve Number</u>	<u>Percent Passing</u>
1 1/2"	100
3/4"	99
3/8"	92
No. 4	75
No. 10	61
No. 50	36
No. 100	19
No. 200	9.0

**DATE SAMPLED:** 3/19/20

**DATE TESTED:** 3/27/20



**CONNIE A. JOHNSON-GEARHART, P.E.**  
Florida License No. 69013

This item has been digitally signed and sealed by Connie A. Johnson-Gearhart, P.E. on the date adjacent to the seal.

Printed copies of this document are not considered signed and sealed and the signature must be verified on any electronic copies.